

**ALLOY SURCHARGE  
SEPTEMBER 2017**

<b>307 Si</b>	<b>1.34</b>
<b>308 L / LSi</b>	<b>1.58</b>
<b>309 L / LSi</b>	<b>1.85</b>
<b>309 LMo</b>	<b>2.31</b>
<b>310</b>	<b>2.44</b>
<b>312</b>	<b>1.72</b>
<b>316 L / LSi</b>	<b>2.04</b>
<b>317 L</b>	<b>2.42</b>
<b>318 Si</b>	<b>2.16</b>
<b>347 Si</b>	<b>1.62</b>
<b>2209</b>	<b>1.95</b>
<b>2594</b>	<b>1.88</b>
<b>410</b>	<b>0.60</b>
<b>410NIMO</b>	<b>0.95</b>
<b>4122</b>	<b>0.81</b>
<b>420</b>	<b>0.55</b>
<b>430</b>	<b>0.63</b>
<b>430 LNB</b>	<b>0.72</b>
<b>385 (904L)</b>	<b>3.33</b>