

DAIKO Srl – Società Unipersonale

Operative Site #1: Via Aquileia, 13-15 - 31048 Olmi di San Biagio di Callalta (Treviso) Italy - Ph. +39 0422 796367

Operative Site #2: Via Toscana, 3A-3B – 20056 Grezzago (MI) ITALY – ph. +39 02 9090477

[technical@daikowelding.com](mailto:technical@daikowelding.com)

[www.daikowelding.com](http://www.daikowelding.com)

## ALLOY SURCHARGE **SEPTEMBER 2019**

<b>307 Si</b>	<b>1.80</b>
<b>308 L / LSi</b>	<b>2.15</b>
<b>309 L / LSi</b>	<b>2.59</b>
<b>309 LMo</b>	<b>3.41</b>
<b>310</b>	<b>3.66</b>
<b>312</b>	<b>2.17</b>
<b>316 L / LSi</b>	<b>3.00</b>
<b>317 L</b>	<b>3.67</b>
<b>318 Si</b>	<b>3.18</b>
<b>347 Si</b>	<b>2.35</b>
<b>2209</b>	<b>2.70</b>
<b>2594</b>	<b>3.17</b>
<b>410</b>	<b>0.57</b>
<b>410NIMO</b>	<b>1.30</b>
<b>4122</b>	<b>0.98</b>
<b>420</b>	<b>0.57</b>
<b>430</b>	<b>0.66</b>
<b>430 LNB</b>	<b>0.79</b>
<b>385 (904L)</b>	<b>5.42</b>

**DAIKO**



**G-TECH**

Please do not read if You are not the intended recipient(s). Any use, reproduction or disclosure by any other person is strictly prohibited. If You have received this e-mail in error, please notify the sender and destroy the original transmission and its attachments without reading or saving it in any manner.